

COUNTY:

TOWN:

## DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street Westminster, Maryland 21157

## WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

CARROLL

MELROSE

	SUFVEY NUMBER: CARR - 1127		
	NEGATIVE FILE NUMBER:		
	UTM REFERENCES: Zone/Easting/Northing		
	U.S.G.S. QUAD. MAP: Manchesta		
	PRESENT FORMAL NAME:		
ORIGINAL FORMAL NAME:			
L	PRESENT USE: Residuce ORIGINAL USE: Residuce ARCHITECT/ENGINEER:		
	BUILDER/CONTRACTOR:		
ĺ	PHYSICAL CONDITION OF STRUCTURE: Excellent ( ) Good (\subseteq) Fair ( ) Poor ( )		
r	THEME: STYLE:		
	DATE BUILT: late 19th c.		


LOCATION: 4254 HANOVER PIKECHOSO) COMMON NAME: Residence FUNCTIONAL TYPE: OWNER: Arthur L. Marker Jr 4254 Hanova Pike ADDRESS: Manchester Md. ACCESSIBILITY TO PUBLIC: Restricted ( ) LEVEL OF SIGNIFICANCE: Local ( ) State ( ) National ( GENERAL DESCRIPTION: Structural System 1. Foundation: Stone (9) Brick () Concrete Wall Structure A. Wood: Log ( ) Post and Beam ( ) Balloon  $(\!\mathcal{K}\!)$ Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block () C. Iron ( ) D. Steel ( ) E. Other 3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal () Aluminum ( ) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( ) Bonding Pattern: Other: Ashestos Sid 4. Roof Structure Other: Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal  $\bigotimes$ Built Up ( ) Rolled ( ) Tile ( ) Other: 6. Engineering Structure: 7. Other: Appendages: Porches (X) Towers () Cupolas () Dormers () Chimneys () Sheds () Ells (') Wings ( ) Other: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead () Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( ) With False Front ( ) Other: Number of Stories: Number of Bays: Entrance Location: Center Approximate Dimensions:

THREAT TO STRUCTURE:					
No Threat (💢 Zoning ( ) Roads	(	)			
Development ( ) Deterioration ( )					
Alteration ( ) Other:	•				

LOCAL ATTITUDES: Positive ( ) Negati

Positive ( ) Negative ( ) Mixed 🞮 Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL	DESCRIPTION:
dentil cornice	4
modern parch	
<b>)</b>	
e.	
,	
RELATED STRUCTURES: (Describe)	
	the state of the s
STATEMENT OF SIGNIFICANCE:	
contributing	
N. S.	
Y <sub>e</sub> .	
REFERENCES: 1862 Martenet's Map:	
1877 LG & S Atlas:	
<u>.</u>	
SURROUNDING ENVIRONMENT: Open Lane ( )Woodland ( )Scattered Bui	ildings() RECORDED BY:
Moderately Built Up (🛩)Densely-Built Up	P() OR VET
Residential ( ) Commercial ( ) Agricultural ( ) Industrial ( )	ORGANIZATION: ( C. Dent. of Planning
Roadside Strip Development ( ) Other:	DATE RECORDED:
other.	DATE RECORDED:





- 1. CARR-1127
- 2. Carroll County, Maryland
- 3. Joe Getty
- 4. July 1985
- 5. Maryland Historical Trust, Annapolis, Md.

- 6. East elevation (camera facing west) 7. 1/1